

× Denotes cut trace, only cut the trace that goes IN BETWEEN the two pads.

Circuit board view is from top.

Denotes through hole components to be added

Due to an error on the last PCBs this cable needs to go directly to the cap